



Changed External Interlock to trip under any condition.
 Changed External Interlock to ignore signals <10ms in length.
 Changed MReset to use one-shot output so reset LED shows.
 ANDed the Overtemp & PhaseFault with the MainPwr output.

Preamp Power Supply Logic Control Circuit

David L. Huffman

August 23, 2000